



Figure 2

* N.C. = CONTACT CLOSED WHEN RELAY NOT POWERED

- NOTES: 1) CUT YELLOW, BROWN AND ORANGE WIRES GOING FROM CONTROL BOX TO BACK-CHECK SWITCH ON OPERATOR CAM.
 2) YELLOW AND ORANGE FROM CAM SWITCH USED FOR COIL ACTIVATION SEE FIGURE 2.
 3) YELLOW TERM (5) BROWN TERM (1) ORANGE TERM (3) FROM CONTROL BOX TO ISO RELAY CONTACTS.

IF AFTER TROUBLESHOOTING A PROBLEM, A SATISFACTORY SOLUTION CANNOT BE ACHIEVED, PLEASE CALL B.E.A., INC. FOR FURTHER ASSISTANCE DURING EASTERN STANDARD TIME AT 1-800-523-2462 FROM 8AM - 5PM. FOR AFTER-HOURS, CALL EAST COAST: 1-866-836-1863 OR 1-800-407-4545 / MID-WEST: 1-888-308-8843 / WEST COAST: 1-888-419-2564. DO NOT LEAVE ANY PROBLEM UNRESOLVED. IF YOU MUST WAIT FOR THE FOLLOWING WORKDAY TO CALL B.E.A., LEAVE THE DOOR INOPERABLE UNTIL SATISFACTORY REPAIRS CAN BE MADE. NEVER SACRIFICE THE SAFE OPERATION OF THE AUTOMATIC DOOR OR GATE FOR AN INCOMPLETE SOLUTION.WEB: WWW.BEASENSORS.COM

		100 ENTERPRISE DRIVE PITTSBURGH, PA 15275 PHONE: (412) 249-4100 FAX: (412) 249-4101 EMAIL: www.beasensors.com	
TITLE:HORTON 4190 W/SAFETY SIDE SUPERSCAN W/BACKCHECK RELAY			
SIZE: B	DRAWN BY: KJG	REV BY: WJR	PART NO: 80.0092.07
	SCALE: NONE	DATE: 21-03-2014	SHEET 1 OF 1

