

NOTES: 1) DOOR CONTROL SW2 SWITCH BANK SET DIP SWITCH #1 AND 3 TO THE OFF (TIMER LOGIC) POSITION.
2) LO21S DIPSWITCHES: 1-5 (LOCK-OUT TIMING), #6-8 (NOT USED)
3) TORQUE IF APPLICABLE AND STALL ADJUSTMENTS MAY NEED TO BE INCREASED FOR LO21S PROPER OPERATION.
4) MAGIC SWING SHOWN, RH MAGIC FORCE, REVERSE FOR LH MAGIC FORCE
5) PLACE A JUMPER FROM TERMINAL #6 TO #8 IF NO BREAK OUT SWITCH IS INSTALLED.

IF AFTER TROUBLESHOOTING A PROBLEM, A SATISFACTORY SOLUTION CANNOT BE ACHIEVED, PLEASE CALL B.E.A., INC. FOR FURTHER ASSISTANCE DURING EASTERN STANDARD TIME AT 1-800-523-2462 FROM 8AM - 5PM. FOR AFTER-HOURS, CALL EAST COAST: 1-866-836-1863 OR 1-800-407-4545 / MID-WEST: 1-888-308-8843 / WEST COAST: 1-888-419-2564. DO NOT LEAVE ANY PROBLEM UNRESOLVED. IF YOU MUST WAIT FOR THE FOLLOWING WORKDAY TO CALL B.E.A., LEAVE THE DOOR INOPERABLE UNTIL SATISFACTORY REPAIRS CAN BE MADE. NEVER SACRIFICE THE SAFE OPERATION OF THE AUTOMATIC DOOR OR GATE FOR AN INCOMPLETE SOLUTION.WEB: WWW.BEASENSORS.COM

BEA
We open up New Horizons
A HALMA GROUP COMPANY

100 ENTERPRISE DRIVE
PITTSBURGH, PA 15275
PHONE: (412) 249-4100
FAX: (412) 249-4101
EMAIL: www.beasensors.com

TITLE: STANLEY MP SINGLE WITH LO21S, PARALLAX 1

SIZE:	DRAWN BY:	REV BY:	PART NO:
A	KJG	WJR	80.0129.03
	SCALE:	DATE:	SHEET
	NONE	13 NOV 2008	1 OF 1