



**NOTES:**

- 1.) CAP OFF UNUSED LO21 WIRES.
- 2.) IF USING TEN PIN CONNECTOR TO CONNECT TO BODY GUARD SET OUTPUT CONFIGURATION ON BODY GUARD TO VALUE 2 (NORMALLY CLOSED).

IF AFTER TROUBLESHOOTING A PROBLEM, A SATISFACTORY SOLUTION CANNOT BE ACHIEVED, PLEASE CALL B.E.A., INC. FOR FURTHER ASSISTANCE DURING EASTERN STANDARD TIME AT 1-800-523-2462 FROM 8AM - 5PM. FOR AFTER-HOURS, CALL EAST COAST: 1-866-836-1863 OR 1-800-407-4545 / MID-WEST: 1-888-308-8843 / WEST COAST: 1-888-419-2564. DO NOT LEAVE ANY PROBLEM UNRESOLVED. IF YOU MUST WAIT FOR THE FOLLOWING WORKDAY TO CALL B.E.A., LEAVE THE DOOR INOPERABLE UNTIL SATISFACTORY REPAIRS CAN BE MADE. NEVER SACRIFICE THE SAFE OPERATION OF THE AUTOMATIC DOOR OR GATE FOR AN INCOMPLETE SOLUTION. WEB: WWW.BEASENSORS.COM

**BEA**  
 We open up New Horizons  
 HALMA GROUP COMPANY  
 100 ENTERPRISE DRIVE  
 PITTSBURGH, PA 15275  
 PHONE: (412) 249-4100  
 FAX: (412) 249-4101  
 EMAIL: www.beasensors.com

**TITLE: TORMAX TTX II SINGLE LO21, PARALLAX I**

|         |               |              |                     |
|---------|---------------|--------------|---------------------|
| SIZE: A | DRAWN BY: JED | REV BY: JED  | PART NO: 80.0234.00 |
|         | SCALE: NONE   | DATE: ddmmyy | SHEET 1 OF 1        |