



75.5194.00

besam™ MP HUB



PUSH TO OPEN




(SEE NOTE 1)



EAGLE



BODYGUARD



QUADSCAN



NOTES:

1. IF A SECOND EAGLE IS REQUIRED, USE EAGLE 2 INPUT.
2. THE SBK-30 BEAM SET (TX AND RX) CAN BE PLUGGED INTO EITHER CONNECTOR.
3. IF A SECOND BODYGUARD IS REQUIRED, USE A "Y" HARNESS (20.5083).

IF AFTER TROUBLESHOOTING A PROBLEM, A SATISFACTORY SOLUTION CANNOT BE ACHIEVED, PLEASE CALL B.E.A., INC. FOR FURTHER ASSISTANCE DURING EASTERN STANDARD TIME AT 1-800-523-2462 FROM 8AM - 5PM. FOR AFTER-HOURS, CALL EAST COAST: 1-866-836-1863 OR 1-800-407-4545 / MID-WEST: 1-888-308-8843 / WEST COAST: 1-888-419-2564. DO NOT LEAVE ANY PROBLEM UNRESOLVED. IF YOU MUST WAIT FOR THE FOLLOWING WORKDAY TO CALL B.E.A., LEAVE THE DOOR INOPERABLE UNTIL SATISFACTORY REPAIRS CAN BE MADE. NEVER SACRIFICE THE SAFE OPERATION OF THE AUTOMATIC DOOR OR GATE FOR AN INCOMPLETE SOLUTION. WEB: WWW.BEASENSORS.COM

100 ENTERPRISE DRIVE
PITTSBURGH, PA 15275
PHONE: (412) 249-4100
FAX: (412) 249-4101
EMAIL: www.beasensors.com

TITLE: BESAM MP HUB WITH PASSPORT PLUS PACKAGE

SIZE: A	DRAWN BY: KJG	REV BY: TUC	PART NO: 80.0237.00
	SCALE: NONE	DATE: 22 NOV 2005	SHEET 1 OF 1