



**NOTES:**

- 1.) SET CONTROL SLIDE SWITCH TO "STANDARD SAFE".
- 2.) ROUTE LO21 RED AND BLACK TO CONTROL ACTIVATION RELAY AS SHOWN. ENSURE THE RED IS CONNECTED TO PIN "A" AND BLACK TO PIN "B".
- 3.) IF INSTALLING ON A PAIR OF OPERATORS PARALLEL 2ND GT RELAY HARNESS WIRES. RED TO RED, BLACK TO BLACK, GREEN TO GREEN, WHITE TO WHITE.
- 4.) CAP OFF UNUSED LO21 WIRES.

IF AFTER TROUBLESHOOTING A PROBLEM, A SATISFACTORY SOLUTION CANNOT BE ACHIEVED, PLEASE CALL B.E.A., INC. FOR FURTHER ASSISTANCE DURING EASTERN STANDARD TIME AT 1-800-523-2462 FROM 8AM - 5PM. FOR AFTER-HOURS, CALL EAST COAST: 1-866-836-1863 OR 1-800-407-4545 / MID-WEST: 1-888-308-8843 / WEST COAST: 1-888-419-2564. DO NOT LEAVE ANY PROBLEM UNRESOLVED. IF YOU MUST WAIT FOR THE FOLLOWING WORKDAY TO CALL B.E.A., LEAVE THE DOOR INOPERABLE UNTIL SATISFACTORY REPAIRS CAN BE MADE. NEVER SACRIFICE THE SAFE OPERATION OF THE AUTOMATIC DOOR OR GATE FOR AN INCOMPLETE SOLUTION.WEB: WWW.BEASENSORS.COM

100 ENTERPRISE DRIVE  
 PITTSBURGH, PA 15275  
 PHONE: (412) 249-4100  
 FAX: (412) 249-4101  
 EMAIL: www.beasensors.com

**TITLE: GYROTECH 300,400 WITH SUPPERSCAN RELAY HARNESS**

SIZE: B	DRAWN BY: TUC	REV BY: JED	PART NO: 80.0248.01
SCALE: NONE	DATE: 26 MAR 2009	SHEET: 1 OF 1	