

NOTES:

- 1) POWER MCLINX, SUPERSCAN VIA EXTERNAL POWER SOURCE. OR CONSULT BEA INC. TECHNICAL SUPPORT.
- 2) DPS (door position switch), SHALL CLOSE WHEN DOOR CLOSES.
- 3) ENSURE COMPLIANCE WITH THE CURRENT ANSI 156.19 STANDARD.

IF AFTER TROUBLESHOOTING A PROBLEM, A SATISFACTORY SOLUTION CANNOT BE ACHIEVED, PLEASE CALL B.E.A., INC. FOR FURTHER ASSISTANCE DURING EASTERN STANDARD TIME AT 1-800-523-2462 FROM 8AM - 5PM. FOR AFTER-HOURS, CALL EAST COAST: 1-866-836-1863 OR 1-800-407-4545 / MID-WEST: 1-888-308-8843 / WEST COAST: 1-888-419-2564. DO NOT LEAVE ANY PROBLEM UNRESOLVED. IF YOU MUST WAIT FOR THE FOLLOWING WORKDAY TO CALL B.E.A., LEAVE THE DOOR INOPERABLE UNTIL SATISFACTORY REPAIRS CAN BE MADE. NEVER SACRIFICE THE SAFE OPERATION OF THE AUTOMATIC DOOR OR GATE FOR AN INCOMPLETE SOLUTION.WEB: WWW.BEASENSORS.COM



100 ENTERPRISE DRIVE PITTSBURGH, PA 15275 PHONE: (412) 249-4100 FAX: (412) 249-4101 EMAIL: www.beasensors.com

LOW ENERGY APPLICATION KNOWING ACT,MCLINX1, SUPERSCAN.DPS

SIZE:	DRAWN BY: JED	REV BY: EOF	PART NO: 80.0276.01
	SCALE:	DATE:	SHEET
	NONE	06 AUG, 2007	1 OF 1

 \forall

