



NOTE: THIS DRAWING DOES NOT COMPLY WITH ANSI 156.10 OR 156.19. BESAM AND BEA REQUEST THAT A BODY GUARD SAFETY SENSOR BE ADDED FOR COMPLIANCE. THIS DIAGRAM IS ONLY INTENDED FOR USE OUTSIDE OF THE USA.

BEA
OPEN UP NEW HORIZONS
HALMA GROUP COMPANY

100 ENTERPRISE DRIVE
 PITTSBURGH, PA 15275
 PHONE: (412) 249-4100
 FAX: (412) 249-4101
 EMAIL: www.beasensors.com

TITLE: BESAM CU-2 WITH EAGLE & APPR & SAFETY SS SCANS

IF AFTER TROUBLESHOOTING A PROBLEM, A SATISFACTORY SOLUTION CANNOT BE ACHIEVED, PLEASE CALL B.E.A., INC. FOR FURTHER ASSISTANCE DURING EASTERN STANDARD TIME AT 1-800-523-2462 FROM 8AM - 5PM. FOR AFTER-HOURS, CALL EAST COAST: 1-866-249-7937 OR 1-866-836-1863/ MID-WEST: 1-800-407-4545 OR 1-888-308-8843 / WEST COAST: 1-888-419-2564. DO NOT LEAVE ANY PROBLEM UNRESOLVED. IF YOU MUST WAIT FOR THE FOLLOWING WORKDAY TO CALL B.E.A., LEAVE THE DOOR INOPERABLE UNTIL SATISFACTORY REPAIRS CAN BE MADE. NEVER SACRIFICE THE SAFE OPERATION OF THE AUTOMATIC DOOR OR GATE FOR AN INCOMPLETE SOLUTION. WEB: WWW.BEASENSORS.COM

| | | | |
|-------|-----------|--------------|------------|
| SIZE: | DRAWN BY: | REV BY: | PART NO: |
| A | WJR | | 80.0297.00 |
| | SCALE: | DATE: | SHEET |
| | NONE | 29 JULY 2008 | 1 OF 1 |