



- NOTES: 1) JUMPERS ARE PLACE ON J1 PINS 1 & 2, J2 PINS 4&5 FOR DRY CONTACTS ON RELAY OUTPUT #1.
 2) PUSHPLATE, MOTION SENSOR, CARD READER MUST BE DRY CONTACT
 3) TRANSFORMER AND BRIDGE RECTIFIER VOLT/AMPERE RATING IS DETERMINED BY CURRENT DRAW OR MAGNETIC LOCK
 4) BRIDGE RECTIFIER SUPPLIED BY OTHERS

IF AFTER TROUBLESHOOTING A PROBLEM, A SATISFACTORY SOLUTION CANNOT BE ACHIEVED, PLEASE CALL B.E.A., INC. FOR FURTHER ASSISTANCE DURING EASTERN STANDARD TIME AT 1-800-523-2462 FROM 8AM - 5PM. FOR AFTER-HOURS, CALL EAST COAST: 1-866-836-1863 OR 1-800-407-4545 / MID-WEST: 1-888-308-8843 / WEST COAST: 1-888-419-2564. DO NOT LEAVE ANY PROBLEM UNRESOLVED. IF YOU MUST WAIT FOR THE FOLLOWING WORKDAY TO CALL B.E.A., LEAVE THE DOOR INOPERABLE UNTIL SATISFACTORY REPAIRS CAN BE MADE. NEVER SACRIFICE THE SAFE OPERATION OF THE AUTOMATIC DOOR OR GATE FOR AN INCOMPLETE SOLUTION.WEB: WWW.BEASENSORS.COM

BEA
 We open up New Horizons
 HALMA GROUP COMPANY
 100 ENTERPRISE DRIVE
 PITTSBURGH, PA 15275
 PHONE: (412) 249-4100
 FAX: (412) 249-4101
 EMAIL: www.beasensors.com

TITLE: MC-25 WITH MAGLOCK, NIGHT MODE SWITCH, AUTOMATIC DOOR

SIZE: A	DRAWN BY: KJG	REV BY: KJG	PART NO: 80.0021.02
	SCALE: NONE	DATE: 19 MAY 2005	SHEET 1 OF 1