




75.5194.00
besam MP HUB




Pre-wired
switch
assembly



EAGLE



(SEE NOTE 1)



BODYGUARD

(SEE NOTE 3)



- NOTES:
1. IF A SECOND EAGLE IS REQUIRED, USE EAGLE 2 INPUT.
 2. THE SBK-30 BEAM SET (TX AND RX) CAN BE PLUGGED INTO EITHER CONNECTOR.
 3. IF A SECOND BODYGUARD IS REQUIRED, USE A "Y" HARNESS (20.5083).

IF AFTER TROUBLESHOOTING A PROBLEM, A SATISFACTORY SOLUTION CANNOT BE ACHIEVED, PLEASE CALL B.E.A., INC. FOR FURTHER ASSISTANCE DURING EASTERN STANDARD TIME AT 1-800-523-2462 FROM 8AM - 5PM. FOR AFTER-HOURS, CALL EAST COAST: 1-866-836-1863 OR 1-800-407-4545 / MID-WEST: 1-888-308-8843 / WEST COAST: 1-888-419-2564. DO NOT LEAVE ANY PROBLEM UNRESOLVED. IF YOU MUST WAIT FOR THE FOLLOWING WORKDAY TO CALL B.E.A., LEAVE THE DOOR INOPERABLE UNTIL SATISFACTORY REPAIRS CAN BE MADE. NEVER SACRIFICE THE SAFE OPERATION OF THE AUTOMATIC DOOR OR GATE FOR AN INCOMPLETE SOLUTION.WEB: WWW.BEASENSORS.COM

BEA 100 ENTERPRISE DRIVE
 PITTSBURGH, PA 15275
 PHONE: (412) 249-4100
 FAX: (412) 249-4101
 EMAIL: www.beasensors.com

TITLE: MP HUB WITH BODYGUARD III AND SBK-30 LOCKOUT BEAM

SIZE: A	DRAWN BY: KJG	REV BY: TUC	PART NO: 80.0236.00
	SCALE: NONE	DATE: 22 NOV 2005	SHEET 1 OF 1