



NOTE: IF REQUIRED TO INHIBIT SAFETY SIDE SUPERSCAN. IT WILL BE NECESSARY TO INSTALL 24V RELAY THROUGH OPEN CHECK MICRO SWITCH. OPEN CHECK MICROSWITCH SHALL TRIGGER RELAY TO SLOW DOOR TO OPEN CHECK SPEED AND INHIBIT SWING SIDE SUPERSCAN SIMOTANEOUSLY. CONTACT B.E.A. TECH SUPPORT FOR SPECIFIC WIRING INSTRUCTIONS.

IF AFTER TROUBLESHOOTING A PROBLEM, A SATISFACTORY SOLUTION CANNOT BE ACHIEVED, PLEASE CALL B.E.A., INC. FOR FURTHER ASSISTANCE DURING EASTERN STANDARD TIME AT 1-800-523-2462 FROM 8AM - 5PM. FOR AFTER-HOURS, CALL EAST COAST: 1-866-836-1863 OR 1-800-407-4545 / MID-WEST: 1-888-308-8843 / WEST COAST: 1-888-419-2564. DO NOT LEAVE ANY PROBLEM UNRESOLVED. IF YOU MUST WAIT FOR THE FOLLOWING WORKDAY TO CALL B.E.A., LEAVE THE DOOR INOPERABLE UNTIL SATISFACTORY REPAIRS CAN BE MADE. NEVER SACRIFICE THE SAFE OPERATION OF THE AUTOMATIC DOOR OR GATE FOR AN INCOMPLETE SOLUTION. WEB: WWW.BEASENSORS.COM

BEA
We open up New Horizons
A HALMA GROUP COMPANY
100 ENTERPRISE DRIVE
PITTSBURGH, PA 15275
PHONE: (412) 249-4100
FAX: (412) 249-4101
EMAIL: www.beasensors.com

**TITLE: GYROTECH MAGNUM CONTROL
LO21B/U, PARALLAX II**

SIZE: A	DRAWN BY: KJG	REV BY: EOF	PART NO: 80.0230.01
	SCALE: NONE	DATE: ddmmyy	SHEET 1 OF 1