



- NOTES: 1) LO21B DIPSWITCHES: 1-5 (LOCK-OUT TIMING), #6 (DOWN/ON), #7 (UP/OFF), #8 (DOWN/ ON).  
 2) LO21B MAY BE SUBSTITUTED BY THE LO21U.  
 3) LH MOTOR SHOWN, REVERSE RED & BLACK ON RH

IF AFTER TROUBLESHOOTING A PROBLEM, A SATISFACTORY SOLUTION CANNOT BE ACHIEVED, PLEASE CALL B.E.A., INC. FOR FURTHER ASSISTANCE DURING EASTERN STANDARD TIME AT 1-800-523-2462 FROM 8AM - 5PM. FOR AFTER-HOURS, CALL EAST COAST: 1-866-836-1863 OR 1-800-407-4545 / MID-WEST: 1-888-308-8843 / WEST COAST: 1-888-419-2564. DO NOT LEAVE ANY PROBLEM UNRESOLVED. IF YOU MUST WAIT FOR THE FOLLOWING WORKDAY TO CALL B.E.A., LEAVE THE DOOR INOPERABLE UNTIL SATISFACTORY REPAIRS CAN BE MADE. NEVER SACRIFICE THE SAFE OPERATION OF THE AUTOMATIC DOOR OR GATE FOR AN INCOMPLETE SOLUTION. WEB: WWW.BEASENSORS.COM



100 ENTERPRISE DRIVE  
 PITTSBURGH, PA 15275  
 PHONE: (412) 249-4100  
 FAX: (412) 249-4101  
 EMAIL: www.beasensors.com

**TITLE: BESAM 300/400 (ETIK) WITH  
 PASSPORT PLUS/ PARALLAX 2  
 SYSTEM (LO21B/U)**

|                   |                  |                    |                               |
|-------------------|------------------|--------------------|-------------------------------|
| SIZE:<br><b>A</b> | DRAWN BY:<br>KJG | REV BY:<br>WJR     | PART NO:<br><b>80.0049.05</b> |
|                   | SCALE:<br>NONE   | DATE:<br>02 JUN 08 | SHEET<br>1 OF 1               |