








SENTRYSCAN





Bodyguard/PassPort Presence Sensor



* RECEIVER (A), EMITTER (A)
RECEIVER (B), EMITTER (B)
WH= WHITE, BL= BLACK



(SEE NOTE 3)



BEA
We open up New Horizons
A HALMA GROUP COMPANY
100 ENTERPRISE DRIVE
PITTSBURGH, PA 15275
PHONE: (412) 249-4100
FAX: (412) 249-4101
EMAIL: www.beasensors.com

TITLE: POWER SWING WITH PASSPORT SYSTEM, LO21B/U

SIZE: A	DRAWN BY: KJG	REV BY: KJG	PART NO: 80.0051.03
	SCALE: NONE	DATE: 07 JULY 05	SHEET 1 OF 1

- NOTES: 1) SAFETY BEAM INPUT TO LO-21B MUST BE A DRY CONTACT.
2) REMOVE JUMPER #7 FROM CSD-1 N.C. CIRCUIT. THIS ALLOWS THE PASSPORT/ BODYGUARD TO SAFETY THE DOOR UPON DETECTION
3) LO21B/U DIPSWITCHES 1 THRU 5 FOR LOCKOUT TIME-SETTINGS WILL VARY. #6 (DOWN/ON), #7 (DOWN/ON), #8 (UP/OFF)

IF AFTER TROUBLESHOOTING A PROBLEM, A SATISFACTORY SOLUTION CANNOT BE ACHIEVED, PLEASE CALL B.E.A., INC. FOR FURTHER ASSISTANCE DURING EASTERN STANDARD TIME AT 1-800-523-2462 FROM 8AM - 5PM. FOR AFTER-HOURS, CALL EAST COAST: 1-866-836-1863 OR 1-800-407-4545 / MID-WEST: 1-888-308-8843 / WEST COAST: 1-888-419-2564. DO NOT LEAVE ANY PROBLEM UNRESOLVED. IF YOU MUST WAIT FOR THE FOLLOWING WORKDAY TO CALL B.E.A., LEAVE THE DOOR INOPERABLE UNTIL SATISFACTORY REPAIRS CAN BE MADE. NEVER SACRIFICE THE SAFE OPERATION OF THE AUTOMATIC DOOR OR GATE FOR AN INCOMPLETE SOLUTION.WEB: WWW.BEASENSORS.COM